

2024/LAN/MLI/077



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: INDORAMA - GEMME PETROCHEMICAL LIMITED

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-LEAK GAS INCIDENT

3. Incident Details

- i. Date of Incident: 16-09-2024 ii. Date first reported:
iii. Date of first investigation: 17-09-2024
iv. Date of follow-up investigation: 18-09-2024
v. Time investigation started: 12:08 pm
vi. Estimated quantity spilled: NON-LEAK

4. Site Details

- i. Site/Location: 8° 08' 08" - INDORAMA (NG) DEWERT LINE AT
ABARA COMMUNIT, ETCHE LGA, R/S
ii. Position of Spill/Leak: N 05° 02' 51.5" W 15
E 006° 59' 39.0"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) GAS LINE (NON-LEAK)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) 2" BALL VALVE INSTALLED ON
THE DEWERT LINE AT 12 O'

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) N/A

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify) 2/1A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

- (a) **Community** (*Indicate name*)

- (b) **Land** (*Indicate area in m²*)

- i. _____
- ii. _____
- iii. _____
- iv. _____
- i. _____
- ii. _____
- iii. _____
- iv. _____


- (c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (d) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (f) **Shoreline/water** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken. NO SAMPLES COLLECTED AT THE TIME OF JIV

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. REPAIR WAS CARRIED-OUT ON THE
DELIVERY LINE IMMEDIATELY AFTER JIV. SURVEIL
ANCE SHOULD BE INTENSIFIED ON THE LINE.

12. Time Investigation ended. 13:45 Hrs