



2025/SAR/050

293

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company:

CANDO ENERGY RESOURCES NIGERIA LIMITED

2. Type of Complaint/Incident:

☐ Oil Pollution

☒ Fire/Explosion

☒ Drilling Mud/Chemical Pollution

☒ Others (Specify)

3. Incident Details

i. Date of Incident:

3/05/2025

ii. Date first reported:

03/05/2025

iii. Date of first investigation:

03/05/2025

iv. Date of follow-up investigation:

v. Time investigation started:

13:06 HRS

vi. Estimated quantity spilled:

0.3145 BBL

4. Site Details

i. Site/Location:

18" TRIBIDABA/BRASS PIPELINE AT BARBARAGENE

ii. Position of Spill/Leak:

5° 00' 01" 40.41" N 04° 30' 54.0"

iii. Spill area

☒ Land

☒ Swamp

☒ Freshwater

☒ Mangrove

☒ Coastline

☒ Near shore

☒ Offshore

☐ Others (Specify)

iv. Structural Controls in Place

☒ Boom

☒ Trenches

☒ Bund Wall

☒ Sorbents

☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 0' Clock

☒ 10 0' Clock

☒ 2 0' Clock

☒ 3 0' Clock

☒ 4 0' Clock

☒ 5 0' Clock

☒ 6 0' Clock

ii. Type of Oil Contaminant

☒ Crude Oil

☒ Condensate

☒ Chemicals

☒ Refined Products

☒ Others (Specify)

iii. Facility

☒ Pipeline

☒ Flow Line

☒ Wellhead

☒ Manifold

☒ Flow Station

☒ Rig

☒ Storage Tank

☒ Compressor Plant

☒ Others (Specify)

iv. Cause of Spill

☒ Corrosion

☒ Equipment Failure

☒ Third Party Interference

☒ Accident

☒ Operational Error

☐ Others (Specify)

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks

☒ Drilled Holes

☒ Blasting

☒ Theft

☒ Acid

☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. BABARAGBENE

ii.

iii.

iv.

(b) Land (Indicate area in m²)i. 34.02 m²

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N/A</u>			

(d) Swamp

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N/A</u>			

(e) River

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N/A</u>			

(f) Shoreline/water

☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>N/A</u>			

8. Photograph/Map/Chart Ref.

☐ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

OANDO ENERGY RESOURCES NIGERIA
LIMITED SHOULD IN, OF THE IMPACTED AREA

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA

1. Serigne Ernest Opanony

Signature 03/05/2025

2.

3.

❖ NUPRC/NMDPRA

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. Avela Happiness

Signature 03/05/2025

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1. OYE MICHAEL OANDO CRV AD 03/05/25

2. OMONSO MIKE OANDO EHSQ 3/5/2025

3.

❖ COMMUNITY

1.

2.

3.