



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unlimited	
Reporting Officer		John Itsueli	
Designation		General Manager, Joint Venture Operations	
Phone Number		0817 207 3917	
Email Address		itsueli@seplatenergy.com	
Incident Number		010 / 2025	
Section 2 - Location			
State / LGA		QIT Tank 5005 / Ibeno	
Coordinates of spill		EASTINGS 4Deg 32Min/55Secs N NORTHINGS 8Deg 1Min/4Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☐ Offshore ☐ Subsea ☐ Swamp Area ☒ Others: Onshore	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		7/1/2025 Time: 05:25 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES	
		☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline	
		PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line	
		STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify).....	
		PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment Failure: During operator round, Crude Movement personnel observed oil flow into the Bundwall of tank 5005. Further checks confirmed that the oil was coming through the roof drain line into the Bundwall area.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☒ Sorbent ☐ Others (specify).....	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
Viscosity			

Oil	Slick Locations(s)		
-----	--------------------	--	--

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
Oil color and appearance	Patches (pa)		
	Silver/grey		
	Rainbow		
	Metallic		
Oil color and appearance	Transitional		
	Dark		
	Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	TBD	
	Coverage		
	Direction of travel		
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)			
Initial Wind Speed			
Air Temperature (C or OF)			
Visibility Estimate		☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood		High ☐ Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning		Yes ☐ No ☒	
Recovery of free phase oil		Yes ☐ No ☒	
Booming		Yes ☐ No ☒	
Wildlife rehabilitation		Yes ☐ No ☒	
Dispersant application		Yes ☐ No ☒	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)
Oil spill team deployed to commence cleanup/evacuation. Absorbent pads were immediately placed to contain the oil.

Section 8– Equipment	
On Site	

REPORTING OFFICER: John Itsueli
DESIGNATION: General Manager, Joint Venture Operations

Initial
FBU

Signed by:
John Itsueli
31AFB6B4837644A...

SIGNATURE:

02-Jul-25 | 20:08 WAT
DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*