



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. **Company:** NIGERIAN ACUP OIL COMPANY (NACOC)
2. **Type of Complaint/Incident:**

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify).....
3. **Incident Details**
 - i. Date of Incident: 23 / 01 / 2016 ii. Date first reported: 23 / 01 / 2016
 - iii. Date of first investigation: 23 / 01 / 2016 iv. Spill Incidence No.: 2016/SAR/018
 - v. Date of follow-up investigation:/...../.....
 - vi. Time investigation started: 10.05 hrs
 - vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. **Site Details**
 - i. Site/Location: 18" TERIDABA/BRASS P/L @ LAGOS/BENE
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IREW
 - iv. Spill Co-ordinates: N(m) 04° 28' 29.1"
E(m) 006° 04' 21.3"
 - v. **Spill area**

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify).....
 - vi. **Structural Controls in Place**

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) NIL
5. **Circumstances Around Spill Point**
 - i. **Visual observation of Hole Position**

☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. **Type of Oil contaminant**

☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify)
 - iii. **Facility**

☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. **Cause Of Spill.**

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify).....
 - v. **Visible Sign of Third Party Interference**

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water

☒ Venerable Objects ☒ Others (specify).....N/A.....

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes

☒ Dead floating crabs ☒ Withering of vegetation ☒ Others...N/A.....

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift

☒ Permanent ☒ Others ..N/A.....

8. Extent of Impact

a) Community (indicate name)

i.

ii.

iii.

iv.

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

h) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

9. Photograph/Map/Chart Rel.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation Nigerian Azip Oil Company should
improve surveillance of their facility.

13. Time investigation ended 1525 hrs

14. Name and Signature of Participants