



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify): CRUDE OIL SPILL
3. Incident Details
i. Date of Incident: 21/09/2016 ii. Date first reported: 21/09/2016
iii. Date of first investigation: 21/09/2016 iv. Spill Incidence No. 2016/SAR/135
v. Date of follow-up investigation: / vi. Time investigation started: 14:03 HRS
vii. Estimated quantity spilled(bbls): 0.143 viii. Quantity Recovered:
4. Site Details
i. Site/Location: 18" TEBDABA / BRASS PIPELINE AT ELEPA
ii. State: BAYELSA iii. L.G.A.: NEMBE
iv. Spill Co-ordinates: N(m) 04° 27' 29.3"
E(m) 006° 10' 26.5"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) CUT-OFF CONE

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland
- ☐ Fish Pond
- ☐ Vegetation
- ☐ Fishing Net
- ☐ Surface water
- ☐ Venerable Objects
- ☒ Others (Specify) NIL

ii. Nature of impact

- ☐ Oil stained vegetation
- ☐ Oil stained fishing nets
- ☐ Dead floating fishes
- ☐ Dead floating crabs
- ☐ Withering of vegetation
- ☒ Others (Specify) Dead trees

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
- ☐ Outside Company's facility/ROW

7. Extent of Impact

- (a) Community (Indicate name)

i. N/A

ii. N/A

iii. N/A

iv. N/A
- (b) Land (Indicate area in m²)

i. N/A

ii. N/A

iii. N/A

iv. N/A

- (c) Creek/Creek lets
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>	<u>N/A</u>	

- (d) Swamp
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>	<u>N/A</u>	

- (e) River
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>	<u>N/A</u>	

- (f) Shoreline/water
- ☐ Tidal
- ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>N/A</u>	<u>N/A</u>	

6. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

7. Samples taken.....

8. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

9. Remarks/Recommendation.....

TIN was conclusive, NAOe
Should increase surveillance of her facilities

10. Time Investigation ended.....

11. Name and Signature of Participants