



2016/SAR/187

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN ACIP OIL COMPANY LTD (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 17/12/2016 ii. Date first reported: 17/12/2016
iii. Date of first investigation: 18/12/2016
iv. Date of follow-up investigation:.....
v. Time investigation started: 13:16 HRS
vi. Estimated quantity spilled: 0.12 BARRELS
4. Site Details
i. Site/Location: 18" TEBIDABO/BRASS PIPELINE @ IGBEMAFORU
ii. Position of Spill/Leak: N 04° 31' 53.9 E 005° 59' 47.4
iii. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify): 3" VALVE INSTALLED WITH PIPE CONNECTION AT 12:00 CLOCK POSITION FOR OIL THEFT

6. Impact of Incident

- i Properties impacted by the incident
 - ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
 - ☐ Venerable Objects ☐ Others (specify).....
- ii. Nature of impact
 - ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 - ☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....
- iii. Delineation of impacted area
 - ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

- a) Community (indicate name)
 - i. ICBEMATORU
 - ii.
 - iii.
 - iv.
- b) Land (indicate area in m²)
 - i. 20 m²
 - ii.
 - iii.
 - iv.
- b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... IMPACT IS MINIMAL DELIMITATION
SURVEY AND REPAIRS COMPLETED. SITE SHOULD
BE LEFT FOR NATURAL ATTENUATION.....

12. Time investigation ended..... 15.59 HRS