



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIA AGIP OIL COMPANY LIMITED
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 08.10.2016 ii. Date first reported: 08.10.2016
 - iii. Date of first investigation: 08.10.2016 iv. Spill Incidence No.: 2016/SAR/144
 - v. Date of follow-up investigation: —/—/—
 - vi. Time investigation started: 1418 HOURS
 - vii. Estimated quantity spilled(bbls): 0.031 viii. Quantity Recovered:
4. Site Details
 - i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT MBIKIBA
 - ii. State: BAYELSA iii. L.G.A.: SOUTHERN IJAW
 - iv. Spill Co-ordinates: N(m) 04° 28' 28.9"
E(m) 006° 07' 12.8"
 - v. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - vi. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify): N/A
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. Cause Of Spill.
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
 - ☐ Others (specify).....



6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) N/A

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others N/A

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others N/A

8. Extent of Impact

a) Community (indicate name)

- i. N/A
 ii. N/A
 iii. N/A
 iv. N/A

b) Land (indicate area in m²)

- i. N/A
 ii. N/A
 iii. N/A
 iv. N/A

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

10. **Samples taken**.....

11. **Investigation carried out by**

☐ Foot ☒ Boat ☐ Aircraft

12. **Remarks/Recommendation**..... SUSPECTED VANDALS) CUT OPEN THE
CONE OF PREVIOUSLY REPAIRED POINT AT 12:00 O'CLOCK
POSITION FOR OIL THEFT ACTIVITIES. INCREASE SURVEI
LLANCE

13. **Time investigation ended** ... 1505 HOURS.