

SOME PHOTOGRAPHS;



-Spill point before excavation.



After excavation showing installed valve.



Cone during repair.



Repaired point with rappers.



Point backfilled after repair.