



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY.
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) N/A
3. Incident Details
i. Date of Incident: 04/01/2017 ii. Date first reported: 04/01/2017
iii. Date of first investigation: 04/12/2017 iv. Spill Incidence No. 2017/SR/NL/001
v. Date of follow-up investigation: /
vi. Time investigation started: 11:35 HRS
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NA
4. Site Details
i. Site/Location: IS" TERUBA/BRASS PIPELINE AT OYEREGBENE
ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAU LOCAL GOVT.
iv. Spill Co-ordinates: N(m) 04°29'43.3"
E(m) 006°64'41.9"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify) N/A
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) N/A
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) NIL
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) N/A
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) N/A
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) 3" VALVE INSTALLED ON A PREVIOUSLY REPAIRED POINT ON THE FACILITY AT 12 O'CLOCK POSITION FOR CRUDE OIL THEFT ACTIVITIES.



6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) N/A

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Delineation of Impacted area

- ☐
- Within Company's facility/ROW
- ☐
- Outside Company's facility/ROW

7. Extent of Impact

- (a) Community (*Indicate name*)

- (b) **Land** (Indicate area in m^2)

N/A

- (c) Creek/Creek lets

- ☐
- Tidal

- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (d) Swamp

- ☐
- Tidal

- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (e) River

- ☐
- Tidal

- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

- (f) Shoreline/water

- ☐
- Tidal

- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation.. NAOC SHOULD BEEP UP SECURITY
ALONG ITS FACILITIES.

12. Time Investigation ended.. 14:00 HRS