



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPMC
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 14TH Dec. 2013 ii. Date first reported: 15TH Dec, 2013
 - iii. Date of first investigation: 17TH Dec. 2013
 - iv. Date of follow-up investigation:.....
 - v. Time investigation started: 12:55 PM
 - vi. Estimated quantity spilled: N/A
4. Site Details
 - i. Site/Location: KM 203, ZA22AGA, S/PAWA AXIS, MUNYA LE
 - ii. Position of Spill/Leak: N 09.78229° E 007.11093 Z 423m NIGER ST
 - iii. Spill area
 - ☒ Land ☐ Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify): RECOVERY PIT
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause Of Spill
 - ☒ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify): N/A

6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water

☐ Venerable Objects ☐ Others (specify).....

IRRIGATION FARMS DOWN STREAM, BUT NOT YET ASCERTAINED

ii. Nature of impact

☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☒ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i. Kumbhade

i.

ii.

ii.

iii.

iii.

iv.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken NO SAMPLE TAKEN

10. Investigation carried out by



☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation IMMEDIATE OIL RECOVERY, CLEANUP AND REMEDIATION OF THE IMPACTED SITE. IMMEDIATE OVERHAUL OF ALL AFFECTED PIPES DAMAGE ASSESSMENT.

12. Time investigation ended 2:30pm

13. Name and Signature of Participants

♦ NOSDRA

1. SAFIYA ABBAS MUHAMMAD 
2. TAHR IBRAHIM I 
3. ISMA'IL YAHYA 

♦ DPR

- 1.
- 2.
- 3.


♦ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

♦ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

♦ COMPANY (PPMC) 17/12/13

1. GOTO, N.W 
- 2.
- 3.

♦ COMMUNITY (KUMBWADA)

1. YERIMA DANJUMA SALIHU (08032697572)
- 2.
- 3.