

INCIDENT NUMBER: 1986368



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

☒ Oil Pollution

☐ Fire/Explosion

☐ Drilling Mud/Chemical Pollution

☐ Others (Specify)

3. Incident Details

i. Date of Incident: 15/12/2017 ii. Date first reported:

iii. Date of first investigation: 22/12/2017

iv. Date of follow-up investigation: 29-30/12/2017

v. Time investigation started: 1300 hours

vi. Estimated quantity spilled: 59 BARRELS

4. Site Details

i. Site/Location: 20' RUMUEKPE-NKPOKU TRANS NIGER PIPELINE, IBAA, EMDITUA, RIVERS STATE

ii. Position of Spill/Leak: N04° 57' 13.2" E006° 49' 57.4"

iii. Spill area

☒ Land

☐ Swamp

☐ Freshwater

☐ Mangrove

☐ Coastline

☐ Near shore

☐ Offshore

☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom

☐ Trenches

☐ Bund Wall

☐ Sorbents

☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O'Clock

☐ 10 O'Clock

☐ 2 O'Clock

☒ 3 O'Clock

☐ 4 O'Clock

☐ 5 O'Clock

☐ 6 O'Clock

ii. Type of Oil Contaminant

☒ Crude Oil

☐ Condensate

☐ Chemicals

☐ Refined Products

☐ Others (Specify)

iii. Facility

☒ Pipeline

☐ Flow Line

☐ Wellhead

☐ Manifold

☐ Flow Station

☐ Rig

☐ Storage Tank

☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion

☐ Equipment Failure

☒ Third Party Interference

☐ Accident

☐ Operational Error

☐ Others (Specify)

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks

☒ Drilled Holes

☐ Blasting

☐ Theft

☐ Acid

☐ Others (Specify) 10mm drill hole

--	--	--

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation SURVEILLANCE SHOULD BE IMPROVED;
THE SITE SHOULD BE CLEANED UP IMMEDIATELY; COMMUNITY ISSUES
SHOULD BE RESOLVED BY SPDC BEFORE CALLING FOR JIN.

12. Time Investigation ended..... 15:10 HOURS