

2013/SAR/458/771



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 21/12/13 ii. Date first reported: 21/12/13
iii. Date of first investigation: 21/12/13
iv. Date of follow-up investigation:
v. Time investigation started: 1035 HRS
vi. Estimated quantity spilled: 80 BBLs

4. Site Details

- i. Site/Location: 18" TEBIDABA/BRASS P/L @ IGBEMATORU
ii. Position of Spill/Leak: N 04° 31' 34.6" E 006°

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) UNKNOWN PERSONS INSTALLED 4" NIPPLE
@ 12 O'CLOCK POSITION ON THE FACILITY.

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☒ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i. IGBEMAJORI

① ii. N04° 31' 34.6" E 006° 00' 27.7"

② iii. N04° 31' 33.4" E 006° 00' 28.9"

③ iv. N04° 31' 33.2" E 006° 00' 28.8"

④ N04° 31' 32.2" E 006° 00' 30.3"

b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

b) Land (indicate area in m²)

⑤ N04° 31' 32.3" E 006° 00' 30.3"

⑥ N04° 31' 32.4" E 006° 00' 30.4"

⑦ N04° 31' 32.2" E 006° 00' 30.3"

⑧ N04° 31' 32.3" E 006° 00' 30.0"

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation. JIW/REPAIRS AND DELIMITATION SURVEY
COMPLETED ON 21/12/13. CLEAN UP REQUIRED AS SOON
AS POSSIBLE. INCREASE IN SURVEILLANCE.