



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: Shell Petroleum Development Company Ltd
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 7/2/2014 ii. Date first reported: 7/2/2014
 - iii. Date of first investigation: 10/2/2014 iv. Spill Incidence No.: 119596
 - v. Date of follow-up investigation: N/A
 - vi. Time investigation started: 17:30 HR
 - vii. Estimated quantity spilled(bbls): 5 bbls viii. Quantity Recovered:
4. Site Details
 - i. Site/Location: 20" Otumare - Escrows P/L @ Adjako 9160
 - ii. State: DELTA iii. L.G.A.: Warri South West
 - iv. Spill Co-ordinates: N(m) 05° 33' 36.2 ~~36.2~~
 - E(m) 005° 12' 09.5"
 - v. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - vi. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) Natural Depression
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
 - iv. Cause Of Spill.
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify): 4" valve welded at 12' o'clock position on the pipe

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... None.....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. Adjulisbo
ii. Adjulisbo
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

10. Samples taken..... No

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation..... Dug and backfilled trench, on
excavation a 4" welded valve was sighted
immediate clean-up and clean-a repairs
recommended.

13. Time investigation ended 18:42 HRS