

2015/LAR/0721



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOTC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) CRUDE OIL SPILL

3. Incident Details

- i. Date of Incident: 03-06-2015 ii. Date first reported: 03-06-2015
iii. Date of first investigation: 03-06-2015
iv. Date of follow-up investigation:
v. Time investigation started: 1145 Hrs
vi. Estimated quantity spilled: 0.046 Bbls

4. Site Details

- i. Site/Location: EBOCHA ST FLOW LINE LEAKAGE @ FERRY RD, EBOCHA.
ii. Position of Spill/Leak: ① N 05° 26' 50.5" S, E 006° 40' 34.0" W
② N 05° 26' 50.3" S, E 006° 40' 34.3" W
③ N 05° 26' 50.3" S, E 006° 40' 34.6" W
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)
iv. Structural Controls in Place
☐ Boom ☐ Trench ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

- i. Visual observation of location
☒ 12 0' Clock - 30th ☐ 1' Clock ☐ 2 0' Clock ☐ 3 0' Clock 11-12 0' clock
☐ 4 0' Clock ☐ 5 0' Clock ☐ 6 0' Clock 12-30 clock
ii. Type of Oil Contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)
iii. Facility
☐ Pipeline ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Separator Plant
☐ Others (Specify)
iv. Cause of Spill
☐ Corrosion ☐ Valve Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Cuts ☐ Drilling ☐ Theft ☐ Acid
☐ Others (Specify) THREE HACKSAW CUTS WERE OBSERVED @
DIFFERENT POINTS ON THE FACILITY.

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. Eboetta

ii. _____

iii. _____

iv. _____

(b) Land (Indicate area in m²)

i. 50.84 m²

ii. _____



iii. _____

iv. _____

(c) Creek/Creek lets

☐ Tidal


☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken.....

NO

10. Investigation carried out by

☐ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation.....

The JUV was carryout successfully.
The spilled oil was immediately mop-up by in-house team.
The repair was done. NAOC should intensified security on its fuel.

12. Time Investigation ended.....

13.05 Hrs.