

2015/LAR/167/443



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 13/11/2015 ii. Date first reported: 13/11/2015
iii. Date of first investigation: 16/11/2015 iv. Spill Incidence No. 2015/LAR/167/443
v. Date of follow-up investigation:
vi. Time investigation started: 14:00 HRS
vii. Estimated quantity spilled(bbls): 11.571 viii. Quantity Recovered: 1.5 BBLs

4. Site Details

- i. Site/Location: TAYLOR CREEK 2L & S F/L @ KALABA AYANABELE/AKUMONI
ii. State: BA/ELSA iii. L.G.A.: YENAGOA
iv. Spill Co-ordinates: N(m) 05° 07' 32.3", 05° 07' 33.5", 05° 07' 34.4"
E(m) 006° 27' 30.3", 006° 27' 30.0", 006° 27' 29.2"

v. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (specify) SEASONAL SWAMP

vi. Structural Controls in Place

- ☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

(9-11 O'CLOCK)

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)

iv. Cause Of Spill.

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☐ Fishing Net
 ☐ Surface water
 ☐ Venerable Objects
 ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☐ Oil stained fishing nets
 ☐ Dead floating fishes
 ☐ Dead floating crabs
 ☐ Withering of vegetation
 ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☐ Fishing net
 ☐ Makeshift
 ☐ Permanent
 ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

399 90

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation THE CAUSE OF SPILL WAS AS A RESULT OF THIRD PARTY INTERFERENCE. THERE WAS A VISIBLE THREE NUMBERS OF 100MM, 110MM AND 105MM. HACK SAW CUT WITHIN 100M DISTANCE ON THE FLOWLINE AT (12, 3, 4 and 9-11) O'CLOCK POSITION 16:20 HRS

13. Time investigation ended

14. Name and Signature of Participants

❖ NOSDRA

1. AGORO, D.S [Signature] 16/11/15
- 2.
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. MONDAY AGUDA [Signature] 16/11/15
- 2.
- 3.

❖ COMPANY

1. BUOLA LAMRIS [Signature] 16/11/15
2. ELUKA. OGBU [Signature] 16/11/15
- 3.
- 4.
- 5.

❖ COMMUNITY

1. BUNAFI NOBLE [Signature] 16/11/2015
- 2.
- 3.
- 4.
- 5.