

2015/LAR/170/446



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIAOC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 13/11/2015 ii. Date first reported: 13/11/2015
iii. Date of first investigation: 17/11/2015 iv. Spill Incidence No. 2015/LAR/170/446
v. Date of follow-up investigation:
vi. Time investigation started:
vii. Estimated quantity spilled(bbls): 11.573 viii. Quantity Recovered: 1 BBL
4. Site Details
i. Site/Location: TAYLOR CREEK 2L & S F/L OKARA/AYAMABELE/AKUMONI
ii. State: BAYELSA iii. L.G.A: YENAGOA
iv. Spill Co-ordinates: N(m) 05° 07' 32.8", 05° 07' 38.1", 05° 07' 38.5"
E(m) 006° 27' 26.7", 006° 27' 26.4", 006° 27' 26.1"
v. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (specify) SEASONAL SWAMP
vi. Structural Controls in Place
☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock [(9-11) O'CLOCK]
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
iii. Facility
☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify)

6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☐ Fishing Net
 ☐ Surface water
 ☐ Venerable Objects
 ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☐ Oil stained fishing nets
 ☐ Dead floating fishes
 ☐ Dead floating crabs
 ☐ Withering of vegetation
 ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☐ Fishing net
 ☐ Makeshift
 ☐ Permanent
 ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²) 399.99

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken NONE

11. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation THE CAUSE OF SPILL WAS AS A RESULT OF THIRD PARTY INTERFERENCE. THERE WAS A VISIBLE THREE NUMBERS OF 110mm, 100mm & 100mm HACK SAW CUT WITHIN 100M DISTANCE ON THE FLOWLINE AT (9-11, 12, 3 & 4) O'CLOCK POSITION

13. Time investigation ended

17:45 HRS

14. Name & Signature of Participants