

PHOTOGRAPHS TAKEN ON SITE



1



2

FIG

1-2: Spill point (already repaired and pre-mopped before JIV)



FIG

3: Impacted area outside company facility (beside Army houseboat)



Fig

4: Impacted area within company facility



5

6: Impacted area within company right of way



6

FIG. 5-



FIG

7: Impacted area within facility