



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Other: (Specify)
3. Incident Details
i. Date of Incident: 22/09/2016 ii. Date first reported: 22/09/2016
iii. Date of first investigation: 23/09/2016 iv. Spill Incidence No.:
v. Date of follow-up investigation:
vi. Time investigation started: 10:05 HRS
vii. Estimated quantity spilled (bbls): viii. Quantity recovered:
4. Site Details
i. Site Location: 6" TUOMO/OGBINBIRI PIPELINE @ LALAGBENE, BAYELSA STATE.
ii. State: BAYELSA iii. LGA: EKEREMOR
iv. Spill Co-ordinates: N(m) 05° 02' 41.1"
E(m) 005° 55' 10.6"
v. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (specify) SEASONAL SWAMP
vi. Structural Controls in Place
☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☒ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause Of Spill:
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☐ Hand saw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☒ Others (specify) INSTALLATION OF 4" NIPPLE @ 10 O' CLOCK POSITION ON THE PIPELINE.



6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i. 295.72
 ii.
 iii.
 iv.

(c) Creek/Creek lets

- ☒ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation (L) CLEAN-UP OF IMPACTED AREA.

(U) IMPROVE SURVEILLANCE AROUND THE FACILITIES

(W) REVIEW/ENHANCE SECURITY AROUND THE ASSETS.

12. Time Investigation ended. 12:41 HRS