



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☐ Others (Specify) (NON LEAK)

3. Incident Details

- i. Date of Incident: 04/06/2017 ii. Date first reported: 04/06/2017
iii. Date of first investigation: 07/06/2017 iv. Spill Incident No: 2017/NL/LAR/013
v. Date of follow-up investigation:
vi. Time investigation started: 3:15PM
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL

4. Site Details

- i. Site/Location: 14" SAMABRI - IDU OIL DELIVERY PIPELINE AT SAM ABRI
ii. State: BAGELSA iii. L.G.A: SALGA
iv. Spill Co-Ordinates: N(m) N05° 16' 34.9"
E(m) E006° 26' 08.1"

v. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock

ii. Type of Oil contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)

iii. Facility

- ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify) (OIL THEFT ACTIVITY)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☒ Theft ☒ Acid
☒ Others (specify)



6. Impact of Incident

i. Properties impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
ii.
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation SURVEILLANCE SHOULD BE BEEFED UP ON THE DELIVERY LINE.

13. Time investigation ended 6:30 PM

14. Name and Signature of Participants

❖ NOSDRA

1. TARIYE OYAKE Signature 07-06-2017
- 2.
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. Obande AKpotu Dsouza Signature 07/06/2017
- 2.
- 3.

❖ COMPANY

1. Jettison Lucky NAOC HSE Signature
2. NILOKIDU GIFT NAOC HSE Signature
3. Wilson Dufabat NAOC ENV. Signature
4. Walter M. Samuel NAOC S&D Signature
- 5.

❖ COMMUNITY

1. Chukwura Ogheneovo youth Leader Signature
2. Enkila Uorighi, Biseni Compound Chief Signature 7/6/17
- 3.
- 4.
- 5.