

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 31/01/2017 ii. Date first reported: 31/01/2017
 - iii. Date of first investigation: 03/02/2017 iv. Spill Incidence No.: 2017/LAR/0171
 - v. Date of follow-up investigation:/...../.....
 - vi. Time investigation started: 15:00 HRS
 - vii. Estimated quantity spilled(bbls): 3 BBLs viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: TAYLOR CREEK 2S FLOWLINE AT KALABA
 - ii. State: BAYELSA iii. L.G.A: YENAGRA
 - iv. Spill Co-ordinates: N(m) N 05° 09' 44.5" E 006° 26' 19.2" (i)
E(m) N 05° 09' 44.0" E 006° 26' 18.8" (ii)
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify).....
 - vi. Structural Controls in Place
 - ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☒ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

POINT (A) 8-11 O'clock position
POINT (B) 1-4 O'clock position
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☐ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
 - iv. Cause Of Spill.
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify).....



i. **Properties impacted by the incident**

☒Farmland ☒Fish Pond ☒Vegetation ☒Fishing Net ☒Surface water
☒Venerable Objects ☒Others (specify).....

ii. **Nature of impact**

☒Oil stained vegetation ☒Oil stained fishing nets ☒Dead floating fishes
☒Dead floating crabs ☒Withering of vegetation ☒Others.....

iii. **Delineation of impacted area**

☒Within Company's facility/ROW ☒Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift
☒ Permanent ☒ Others

8. **Extent of Impact**

a) **Community** (indicate name)

i. KALABA
 ii.
 iii.
 iv.

b) **Land** (indicate area in m²)

i. 25m²
 ii.
 iii.
 iv.

h) **Creeks/Creek lets**

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp**

☒Tidal

☒Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River**

☒Tidal

☒Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken. *NIL*

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation *The impacted site should be cleaned up immediately and the Nigeria Agip oil company should intensify surveillance on its facility.*

13. Time investigation ended *16:00 HRS*