



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 16 / 02 / 2017 ii. Date first reported: 16 / 02 / 17
 - iii. Date of first investigation: 16 / 02 / 2017 iv. Spill Incident No: 2017/SAR/017/036
 - v. Date of follow-up investigation: 19, 20 / 02 / 2017 vi. Time investigation started: 01-03/03/2017
 - vii. Estimated quantity spilled(bbls): 53 Bbls viii. Quantity Recovered: 3 Bbls
4. Site Details
 - i. Site/Location: 16' CLOUGH CREEK / TEBIDABA P/L @ GBARAUN
 - ii. State: BAYELSA iii. L.G.A:
 - iv. Spill Co-Ordinates: N(m) 04° 47' 05.3"
E(m) 005° 47' 13.1"
 - v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify): RIVER CROSSING
 - vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock } N/A
 - ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
 - iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause of Spill
☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☒ Others (specify): CLAMP FAILURE
 - v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify): N/A



6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) MAINLY XIAN GROOVE

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (*indicate name*)

- i. GBARAUN
- ii. NEIGHBOURING COMMUNITIES -
- iii. ~~_____~~
- iv. ~~_____~~

b) Land (indicate area in m^2)

- i. { 280,000 m²)
ii.
iii.
iv.

b) Creeks/Creek lets

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. (u) RECOVERY OF THE FREE
PHASE CRUDE OIL
(u) IMMEDIATE CLEAN-UP OF IMPACTED AREA.

13. Time investigation ended