



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) UNKNOWN PERSON(S) CUT AND CARRIED AWAY ABOUT 200M 4" PIPE.

3. Incident Details

- i. Date of Incident: 12-12-2017 ii. Date first reported: 12-12-2017
iii. Date of first investigation: 15-12-2017
iv. Date of follow-up investigation:
v. Time investigation started: 1225 HRS
vi. Estimated quantity spilled: 4.23 BBLs

4. Site Details

- i. Site/Location: EBEGORO 2T FLOWLINE OMORU ONEGA, RIVERS STATE
ii. Position of Spill/Leak: N05°21'46.2" E006°39'48.4"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☒ 10 0'Clock ☒ 2 0'Clock ☒ 3 0'Clock
☒ 4 0'Clock ☒ 5 0'Clock ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident**i. Properties Impacted by the incident**

- ☒ Farmland ☐ Fish Pond ☐ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact**(a) Community** *(Indicate name)***(b) Land** *(Indicate area in m²)*

- i. OMOKU i. 350.03m²
ii. ii.
iii. iii.
iv. iv.

(c) Creek/Creek lets☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water☐ Tidal☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken.....

NO

10. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

11. Remarks/Recommendation.....

CRUDE OIL IMPACTED AREA SHOULD BE CLEAN-UP IMMEDIATELY
NAOC SHOULD REPLACE THE HARVESTED FLOWLINE
NAOC SHOULD IMPROVE SURVEILLANCE ON THE FLOWLINE

12. Time Investigation ended.....

1330HRS