



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY [NAOC]
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 27.07.2018 ii. Date first reported: 27.07.2018
iii. Date of first investigation: 30.07.2018 iv. Spill Incident No: 2018/LAR/100/127
v. Date of follow-up investigation:
vi. Time investigation started: 15:00 HRS
vii. Estimated quantity spilled(bbls): 2.46 viii. Quantity Recovered: NIL
ix. AKUMONT
4. Site Details
i. Site/Location: TAYLOR CREEK 265 FIL AT KALABA / AYAMABELE
ii. State: BAYELSA iii. L.G.A.: YENAGOA
iv. Spill Co-Ordinates: N(m) SP5: 05° 07' 41.1" SP6: 05° 07' 39.5"
E(m) SP5: 006° 27' 25.1" SP6: 006° 27' 26.4"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☒Farmland ☒Fish Pond ☒Vegetation ☒Fishing Net ☒Surface water
☒Venerable Objects ☒Others (specify).....

ii. Nature of impact

- ☒Oil stained vegetation ☒Oil stained fishing nets ☒Dead floating fishes
☒Dead floating crabs ☒Withering of vegetation ☒Others.....

iii. Delineation of impacted area

- ☒Within Company's facility/ROW ☒Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒Fish Farm/ Pond ☒Fishing Net ☒Makeshift
☒Permanent ☒Others

8. Extent of Impact

a) Community (indicate name)

- i.
ii.
iii.
iv.

b) Land (indicate area in m²)

- i. 177.793
ii.
iii.
iv.

b) Creeks/Creek lets ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

c) Swamp ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

d) River ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation. NAOC SHOULD INTENSIFIED SURVEILLANCE
ON THE FACILITY
AND ALSO CLEAN UP THE IMPACTED AREA
IMMEDIATELY.

13. Time investigation ended..... 17:07 HRS