



2659606

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 4TH JUNE, 2020 ii. Date first reported: 5TH JUNE 2020
iii. Date of first investigation: 7TH JUNE, 2020
iv. Date of follow-up investigation: NIL
v. Time investigation started: 14:46 HRS
vi. Estimated quantity spilled: 20 BBLs

4. Site Details

- i. Site/Location: 14" OKORDIA-RUMUCHE P/L ULA-IKATA
ii. Position of Spill/Leak: (U) S: 04919, T: 58502 (W) S: 04907 6.58513
iii. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock [9 O'CLOCK]

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify) (DRILLING MISTAKE)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify) (SABOTAGE)

Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. ULA - IKATA

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 1,500 m²

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation.....

SPDC should meet the demands of the community (Ula-Iketa) to avoid future occurrence.

15:10 Hrs.

12. Time Investigation ended.....

13. Name and Signature of Participants

❖ NOSDRA

1.

Enem

Akachukwu

07/06/2020

2.

3.

❖ DPR

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1.

KURUYE, J-O

07/06/2020

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1.

OKERINDE SOLOMON

07/06/2020

2.

3.

❖ COMMUNITY

1.

GODDAY EKPOR

07/06/2020

(08145436809)

2.

3.