

AKINIMA 3

2021/LAR/064/106


 NOS° 05' 56.3'
 E006° 27' 45.4"

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Nigerian Agip Oil Company (NAOC)

2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify) Condensate

3. Incident Details

i. Date of Incident: 15-7-2021 ii. Date first reported: 15-7-2021

iii. Date of first investigation: 16-7-2021

iv. Date of follow-up investigation:

v. Time investigation started: 4:40 PM

vi. Estimated quantity spilled: 0.437 barrels

4. Site Details

i. Site/Location: Oshie 15hs Flowline @ Akinima, Ahead of west LCA, Rivers state

ii. Position of Spill/Leak: 5-8° clock position
one hacksaw cut of 80mm in length

iii. Spill area

☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline

☒ Near shore ☒ Offshore ☒ Others (specify)

iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify) contained in a pit excavated by third party

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock

☐ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock 7 o'clock and 8 o'clock

ii. Type of Oil contaminant

☐ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products

☒ Others (specify)

iii. Facility

☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig

☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)

iv. Cause Of Spill

☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident

☒ Operational Error ☒ Others (specify)

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

☒ Others (specify)