



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LTD (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 26/05/19 ii. Date first reported: 26/05/19
iii. Date of first investigation: 27/05/19 iv. Spill Incident No.: 2019/SAR/008/112
v. Date of follow-up investigation: —/—/—
vi. Time investigation started: 14:36 HRS
vii. Estimated quantity spilled(bbls): 15 BBLs iii. Quantity Recovered: 3 BBLs
4. Site Details
i. Site/Location: 10" CROUCH CREEK (TEBIDABA P/L @ EGBEMA ANKALABIR
ii. State: BAYELSA iii. L.G.A.:
iv. Spill Co-Ordinates: N(m) 04° 50' 24.0"
E(m) 005° 41' 45.2"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☒ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....
VISIBLE SIGNS OF HACK SAW CUTS TO INFLECT TWO CUTS (A) 140MM FROM 1 TO 3 O'CLOCK AND (B) 9-11 O'CLOCK POSITION AND A BLAST CAUSING A DENT TO THE PIPELINE @ 6 O'CLOCK.



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others

8. Extent of Impact

a) Community (indicate name)

i. EGSEMA ANGALABIRI

ii.

iii.

iv.

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>EGSEMA ANGALABIRI</u>			

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken..... - AIL -

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation..... IMPACT EXTENDED OUTSIDE RIGHT
OF WAY AND REQUIRES CLEANUP. REPAIRS COMPLETED
ON 27/05/2019. NAOC SHOULD IMPROVE ON SURVEILLANCE.

13. Time investigation ended.....