



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 19.02.19 ii. Date first reported: 19.02.19
iii. Date of first investigation: 27.02.19 iv. Spill Incident No.: 2019/LAR/CL/008
v. Date of follow-up investigation: / /
vi. Time investigation started: 15:21 HRS
vii. Estimated quantity spilled(bbls): GAS LEAK viii. Quantity Recovered: N/A
4. Site Details
i. Site/Location: 6th TUMU-OGBOGBIRI DELVEY GAS LINE OGBOMOSOKE
ii. State: BAVELSA iii. L.G.A: EREREMOR
iv. Spill Co-Ordinates: N(m) 04° 56' 51.4
E(m) 005° 56' 08.9
v. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock 9-10 clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify) GAS LEAK
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify) 100mm HACK SAW CUT INFLECTED AT 9oclock TO 10 clock POSITION
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) 100mm HACK SAW CUT INFLECTED ON THE LINE AT 9.0 clock TO 10 clock POSITION



6. Impact of Incident

i Properties impacted by the incident

- ☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☐Surface water
☐Venerable Objects ☐Others (specify).....

ii. Nature of impact

- ☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
☐Dead floating crabs ☐Withering of vegetation ☐Others.....

iii. Delineation of impacted area

- ☒Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing Net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. Ogbojuwari
ii.
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.



b) Creeks/Creek lets

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			



c) Swamp

- ☐Tidal ☐Non-tidal


NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

d) River

- ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
			

9. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

10. **Samples taken**.....

— Nil —

11. **Investigation carried out by**

☒ Foot ☒ Boat ☐ Aircraft

12. **Remarks/Recommendation**.....

AREA REQUIRES NO FURTHER
INTERVENTION AND RECOMMENDED FOR CLOSE-OUT.
NAC SHOULD IMPROVE IN SURVEILLANCE

13. **Time investigation ended**.....