

3069741



# **NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**

## **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Shell Petroleum Development Company (SPDC)
2. Type of Complaint/Incident:
  - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
  - ☐ Others (Specify).....
3. Incident Details
  - i. Date of Incident: 30/11/2021 ii. Date first reported: 01/12/2021
  - iii. Date of first investigation: 3/12/2021 and 4/12/2021
  - iv. Date of follow-up investigation:.....
  - v. Time investigation started: 2.00 p.m
  - vi. Estimated quantity spilled: 1 bbl
4. Site Details
  - i. Site/Location: 36" Nisporu-Bomu Pipeline, Enaka, Obio/Ak
  - ii. Position of Spill/Leak: A 2" nipple and another 2" ball valve in  
at 12 o'clock position
  - iii. Spill area
    - ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
    - ☐ Near shore ☐ Offshore ☐ Others (specify) and a seasonal Swamp
  - iv. Structural Controls in Place
    - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) None
5. Circumstances Around Spill Point
  - i. Visual observation of Hole Position
    - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
    - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
  - ii. Type of Oil contaminant
    - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
    - ☐ Others (specify) .....
  - iii. Facility
    - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
    - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
  - iv. Cause Of Spill
    - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
    - ☐ Operational Error ☐ Others (specify).....
  - v. Visible Sign of Third Party Interference
    - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
    - ☐ Others (specify).....