



National Oil Spill Detection and Response Agency

FORM B

RISK BASED ASSESSMENT OF OIL SPILL INCIDENCE (RBA)

Note: This report must be submitted within 2 weeks of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mike McAdie	
Phone Number		0812068193	
Email Address		mike.mcadie@exxonmobil.com	
Incident Number		18 / 2022	
Incident Date		10/18/2022	
Spill Stopped Date		10/18/2022	
Section 2 – Location			
Facility Address		Ubit PP / OML 67 - 4 15.32N / 8 11.5E	
State/ LGA		Akwa Ibom State / Ibeno	
Location OML:	OML 67	GPS Coordinate	N 8 11.5E E 4 15.32N
Section 3 – Spill Details			
Date and Time of site assessment		10/19/2022	
Cause of spill	Company ☐ Corrosion ☒ Equipment Failure ☐ Operational/ Maintenance Error ☐ Bund wall overflow	Third Party Interference ☐ Vandalization ☐ Oil Theft ☐ Illegal Refining ☐ Others	Others ☐ Accident ☐ Mystery
Estimated Quantity Spilled (bbl)		About 0.03145bbl of Crude Oil based on sheen appearance	
Estimated Quantity Recovered		None	
Control Measures		☐ Clamping ☐ Well Shut-in ☒ Valve Shut-in ☐ Flow Station Shut Down ☒ Others (specify): Platform was accessed and wells properly secured. Intermittent gas bubbles from relief line already stopped before vessel arrived.	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tankers ☐ Tank Trucks ☐ Barge ☐ Tanker Vessel ☐ Pipeline	
		PIPELINE (Specify pipeline diameter.....) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Delivery line ☐ Export Line ☐ Gas Line	

		STORAGE TANKS ☐ Underground Storage Tank ☐ Above-Ground Storage Tanks ☐ Others (specify).....
		PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow Station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Others (specify).....
Section 4 – Basic Types of Oil		
Very Light Oil		☐ Jet oil or Gasoline
Light Oil		☐ Diesel ☐ No. 2 fuel oil ☒ Light Crude
Medium Oil		
Heavy Oil		☐ Heavy crude oil ☐ Bunker C ☐ No.6 Fuel oil
Section 5 – Site Characterization		
Land Use		
Topography		☐ Sand beach ☐ Dock ☐ Shoreline ☐ Swamp ☐ Others (specify).....
Surficial Geology		Soil Type ☐ Sandy ☐ Clay ☐ Silt ☐ Loam ☐ Peat
		Soil Texture ☐ Very Fine ☐ Fine ☐ Medium ☐ Coarse ☐ Very Coarse
		Soil Structure ☐ Granular ☐ Blocky ☐ Prismatic
		Soil Permeability ☐ Slow ☐ Moderate ☐ Rapid ☐ Permeable ☐ Semi Permeable ☐ Impermeable
		☐ Potential preference pathway for ground water flow
		☐ Potential preferences pathway to ground water
Surrounding Population		☐ Industrial ☐ Residential ☐ Shoreline ☐ Rural ☐ Unpopulated ☐ Others (specify).....
Section 6 - Weather		
	Sea Conditions	☒ Calm ☐ Rough ☐ Not Applicable ☐ Low Tide ☐ High Tide
	Weather Conditions	☐ Bright Sunny ☐ Partly Cloudy ☐ Slight Rain ☒ Others (specify): Clear
	Temperature	30°C
	Wind Direction	South West
	Wind Speed	1 knots
	Relative Humidity	

Section 7 – Receptor Assessment					
Sensitive Receptor	Pathway Impacted Area(m ²)	Distance to Impacted Area(m ²)	Estimated Area of Impact Area(m ²)	Receptor Impacted (Yes/No)	Remarks
Farmland					
Fish Pond					
Vegetation					
Surface Water					
Ground Water					
Venerable Object					
Human Habitation					
Wild Life					
Livestock					
Plantation					
Swamp					

GENERAL REMARK (to include visual observations on impacted area)

[GeneralRemarks]

.....

REPORTING OFFICER: Mike McAdie

DESIGNATION: General Manager, Joint Venture Operations

DocuSigned by:

IMDA ESSLEN

05F1E23059D64A0...

DocuSigned by:

Mike McAdie

B95629AF006040E...

October 31, 2022

SIGNATURE:

DATE:

**Clean-up program report must be submitted within 2 weeks of spill incidence.*