



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		001 / 2023	
Section 2 - Location			
State / LGA		QIT – BOP	
Coordinates of spill		EASTINGS 4Deg 14Min/11Secs N NORTHINGS 8Deg 2Min/24Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		1/12/2023 Time: 05:45 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Corrosion: During export into MT Nave Spherical. A PSV at BOP activated and relieved into Surge tank. Export was discontinued immediately. Investigation ongoing.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): The valve on the sight glass closed and the leak stopped	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release	Continuous Release	
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.01813 bbls of crude oil based on sheen appearance	
	Coverage	About 300m x 10.3m of 70% barely discernible; 10% rainbow colors; 10% silvery sheen; 8% light brown sheen and 2% darkening bands of colors on sea water	
	Direction of travel	West	
Section 5 - Weather			
METEOROLOGICAL DATA		NIMET weather forecast	
Wind Direction (wind direction given from)			
Initial Wind Speed			
Air Temperature (C or OF)			
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐ Ebb ☐		
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	Yes ☐	No ☒	
Recovery of free phase oil	Yes ☐	No ☒	
Booming	Yes ☐	No ☒	
Wild life rehabilitation	Yes ☐	No ☒	
Dispersant application	Yes ☐	No ☒	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark Fraser

DESIGNATION: For: General Manager, Joint Venture Operations

DocuSigned by:
Hashim Sa'idu

4C2D837D2AA148C...

DocuSigned by:
Shane Large

6EC5DAC54B38492...

SIGNATURE:

January 12, 2023

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*