



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		Email Address mark.w.fraser@exxonmobil.com	
Incident Number		002 / 2023	
Section 2 - Location			
State / LGA		Ekpe PP OML 70 - /	
Coordinates of spill		EASTINGS 4Deg 10Min/8Secs N NORTHINGS 8Deg 8Min/21Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		1/19/2023 Time: 10:50 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES	
		☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline	
		PIPELINE (Specify pipeline diameter)	
		☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line	
		STORAGE TANKS	
		☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify).....	
		PRODUCTION FACILITIES	
		☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Corrosion: At 1050hrs 19th Jan., 2023, a personnel carrying out routine checks in the plant observed oil streak from cellar deck of OP. This was traced to a pin-hole leak from a corroded point on a 2" liquid discharge line from Condensate Pumps discharge to Separator B. There was no impact on personnel	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify)): OIM Regular surveillance	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		

	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release		
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00001 bbl of Condensate based on sheen appearance		
	Coverage	About 10m X 1m of 100% silvery sheen on sea water		
	Direction of travel			

Section 5 - Weather

METEOROLOGICAL DATA

Wind Direction (wind direction given from)	North East	NIMET weather forecast
Initial Wind Speed	3knots	
Air Temperature (C or OF)	28°C	
Visibility Estimate	☐ Good ☐ Fair ☐ Poor Hazy	

OCEANOGRAPHIC DATA

Water Current Speed		NIMET weather forecast
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐ No ☒
Recovery of free phase oil	Yes ☐ No ☒
Booming	Yes ☐ No ☒
Wild life rehabilitation	Yes ☐ No ☒
Dispersant application	Yes ☐ No ☒

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: **Mark Fraser**
DESIGNATION: **General Manager, Joint Venture Operations**

DocuSigned by:

 DD6F671808794FD...

DocuSigned by:

 E80C423DA74246A...

January 20, 2023

SIGNATURE:

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*