




NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY [NAOC]
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 11/02/2023 ii. Date first reported: 11/02/2023
iii. Date of first investigation: 12/02/2023 iv. Spill Incident No.: 2023/SAR/031
v. Date of follow-up investigation:
vi. Time investigation started: 09:48 HRS
vii. Estimated quantity spilled(bbls): 0.1606 viii. Quantity Recovered: MOPPED UP
4. Site Details
i. Site/Location: 14" OGBONBIRI/TEBIDABA P/L AT KEME-EBIAMA
ii. State: BAYELSA iii. L.G.A.: SOUTHERN IJAIN
iv. Spill Co-Ordinates: N(m): 04° 47' 05.6"
E(m): 005° 58' 36.1"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify): SHUT-IN
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Jacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify): 2" VALVE INSTALLATION



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

- ☒
- Within Company's facility/ROW
- ☒
- Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☒ Others

8. Extent of Impact

a) **Community** (*indicate name*)

- 
- Handwriting practice lines with two slanted lines drawn across them, starting from the bottom line and ending at the top line.

b) Land (indicate area in m^2)

- i. 96-351
- ii. //
- iii. //
- iv. //

b) Creeks/Creeklets

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A.	

c) Swamp

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

d) **River**

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	N/A		

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
		N/A	

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken..... N/A

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation. NAOC SHOULD INTENSIFY
SURVEILLANCE ON ITS FACILITIES.

13. Time investigation ended..... 11:12 HRS