

2028-1051541



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

☒ Oil Pollution

☐ Fire/Explosion

☐ Spilling Mud & Chemical Pollution

3. Incident Details

i. Date of Incident 15/04/2023

ii. Date first reported 16/04/2023

iii. Date of first investigation 19/04/2023

iv. Date of follow up investigation

v. Time investigation started 2:11hrs

vi. Estimated quantity spilled N/A

4. Site Details

i. Site location 25" Kolo-Coke Creek - Rumuope Pipeline at Okporo

ii. Position of Spill from 4" T70762M; 6639834E

iii. Spill area

☒ Wet and

☐ Dry area

☐ Fresh water

☐ Seawater

☐ Contaminated

iv. Structural Controls in Place N/A

☐ Dike

☐ Fences

☐ Bund wall

☐ Berms

☐ Others (specify)

5. Circumstances Around Spill Point:

i. Visual observation of Hole Position

☒ 12 O' Clock

☐ 10 O' Clock

☐ 8 O' Clock

☐ 6 O' Clock

☐ 4 O' Clock

☐ 2 O' Clock

☐ 12 O' Clock

☐ 10 O' Clock

☐ 8 O' Clock

☐ 6 O' Clock

☐ 4 O' Clock

☐ 2 O' Clock

☐ 12 O' Clock

☐ 10 O' Clock

☐ 8 O' Clock

☐ 6 O' Clock

☐ 4 O' Clock

☐ 2 O' Clock

☐ 12 O' Clock

☐ 10 O' Clock

☐ 8 O' Clock

☐ 6 O' Clock

☐ 4 O' Clock

☐ 2 O' Clock

☐ 12 O' Clock

☐ 10 O' Clock

☐ 8 O' Clock

☐ 6 O' Clock

☐ 4 O' Clock

☐ 2 O' Clock

☐ 12 O' Clock

25" pipeline at 12 o'clock position by unknown person(s).

2028-1051541

a. Impact of Incident

N/A

i. Properties impacted by the incident

- ☐ Wetland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Vulnerable Objects ☐ Others (specify) _____
 ii. Nature of impact N/A

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others _____
 iii. Indication of impacted area N/A

- ☐ Within Company's facility/R.O.W ☐ Outside Company's facility R.O.W

7. Extent of Impact

a) Community (include names)

- i. _____
 ii. _____
 iii. _____
 iv. _____
 b) Land (include area in m²)
 i. _____
 ii. _____
 iii. _____
 iv. _____

b) Creek/Creek beds

☐ Total

☐ Non-total

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

c) Township

☐ Total

☐ Non-total

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

d) River

☐ Total

☐ Non-total

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

e) Shoreline/water

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

8. Photograph/Map/Chart Ref

☒ Still photographs ☐ Video coverage ☐ Mapping

Samples taken..... NIL

Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft Gun

Remarks/Recommendation 3:13hrs

SPDC should remove the illegal connection and repair the
pipeline (2) SPDC should improve on the security of the pipeline

Investigation ended 3:13hrs