

2023_1036084



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) Illegal Connection

3. Incident Details
 i. Date of Incident: 06/04/2023 ii. Date first reported: 07/04/2023
 iii. Date of first investigation: 07-04-2023
 iv. Date of follow-up investigation: _____
 v. Time investigation started: 4:55 HRS
 vi. Estimated quantity spilled: N/A

4. Site Details 36" Rumuckpe-Naame Pipeline at 16ag, Envel
 i. Site/Location: 36" Rumuckpe-Naame Pipeline at 16ag, Envel
 ii. Position of Spill/Leak: 4.953502 N, 6.832824 E
 iii. Spill area: N/A
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify): _____
 iv. Structural Controls in Place: N/A
☐ Boom ☐ Trenches ☐ Bund wall ☐ Checkouts ☐ Others (specify): _____

5. Circumstances Around Spill Point
 i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (specify) NO Leak
 iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify): _____
 iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify): _____
 v. Visible Sign of Third Party Interference
☐ Hack Saw Marks ☐ Drilled Holes ☐ Blasting ☐ Other ☐ Acid
☒ Others (specify) 3" ball valve illegally installed on the pipeline at 12 O'clock position by unknown person(s).

6. Impact of Incident

i. Properties impacted by the incident

N/A

☐ Bermland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Vulnerable Objects ☐ Others (specify) _____

ii. Nature of impact

N/A

☐ Soil stained vegetation ☒ Not stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others _____

iii. Delineation of impacted area

N/A

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate nature)

b) Land (indicate area in m²)

i. _____

i. _____

ii. _____

ii. _____

iii. _____

iii. _____

iv. _____

iv. _____

b) Creeks/Rock hole

☐ Divided

☐ Non-divided

c) Swamp

☐ Divided

☐ Non-divided

d) River

☐ Divided

☐ Non-divided

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

NAME	DIRECTION OF SLACK	LENGTH OF SLACK	WIDTH OF SLACK

1. Photograph/Malware Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

2. Samples taken

4/17

10. Investigations carried out by

☒ Civil

☐ Police

☐ Aircrew

11. Remarks/Description of activities

1) SPDC should remove the illegal
concealment and ensure the privacy of the
2) SPDC should ensure the security of the
5/23/15

12. Time investigation ended

5/23/15