

2022 957394

6



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:
 - ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify): Illegal Connection
3. Incident Details
 - i. Date of Incident: 5/03/2023 ii. Date first reported: 5/03/2023
 - iii. Date of first investigation: 22-03-2023
 - iv. Date of follow-up investigation: 12/25/23
 - v. Time investigation started: N/A
 - vi. Estimated quantity spilled: N/A
4. Site Details
 - i. Site Location: 28" Bonny-Bonny Trans Niger Pipeline at Chobichin
 - ii. Position of Spill/Leak: N4.56754, E7.25033
 - iii. Spill area
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify): N/A
 - iv. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Band wall ☐ Sorbents ☐ Others (specify): N/A
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify): N/A - LEAKING
 - iii. Facility
 - ☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify): N/A
 - iv. Cause Of Spill
 - ☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify): N/A
 - v. Visible Sign of Third Party Interference
 - ☐ Hack saw Marks ☐ Drilled Holes ☐ Blasting ☐ Other ☐ Acid
 - ☐ Others (specify): 28" Pipeline at 12 O'clock position

23/03/2023

6. Impact of Incident

i. Properties impacted by the incident **N/A**

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) _____

ii. Nature of Impact **N/A**

☐ Oil stained vegetation ☐ Oil stained fishing net ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others _____

iii. Delineation of impacted area **N/A**

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate number)

i. _____
 ii. _____
 iii. _____
 iv. _____

b) Land (indicate area in m²)

i. _____
 ii. _____
 iii. _____
 iv. _____

c) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

f) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.

H/A

10. Investigation carried out by

☐ Foot

☐ Boat

☐ Aircraft

Swamp buggy

11. Remarks/Recommendation

(1) SPDC should remove the
illegal connection and repair the line.

(2) SPDC should ensure security of the pipeline.

12. Time investigation ended.

2:25 HRS

13. Name and Signature of Participants