



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Universal Energy Resources Limited (UERL)	
Reporting Officer		Ojubayo Selayu	
Designation		HSE Manager	
Phone Number		07064106884	
Email Address		Ojubayo.Selayu@savannah-energy.com	
Incident Number		UERL/HSE/004	
Section 2 – Location			
State/ LGA		Akwa Ibom State / Mbo / Ibeno LGA	
Coordinates of spill			
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☐ Offshore ☐ Subsea ☒ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		21/10/2022	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker/Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☒ Pipeline PIPELINE (Specify pipeline diameter... 6. inch...) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Delivery line ☒ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... N/A PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☒ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill			
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☒ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☐ Others (specify).....	
Product Data		☐ Persistent	☐ Non Persistent
	Product Name/Type	Crude oil	
	SG/API Gravity	0.75	
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick location(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil	into immediate pipeline environment	
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark	Dark Green	
	Mousse		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others... <u>By Land</u>	
Section 4 - Approximate Duration			
Release Rate	Instantaneous Release	Continuous Release	
	Residue oil contained in the pipeline	Per hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	2.5 bbls	
	Coverage	200m	
	Direction of travel	-	
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)	N/A		
Initial Wind Speed	N/A		
Air Temperature (°C or °F)	N/A		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed	N/A		
Tide Phase: Flood	High ☐ Ebb ☐		
Water Temperature (°C or °F)			
High Tide Time			
Source			
Section 6 - Pre-Entry Activities			
Mechanical cleaning	Yes ☒	No ☐	
Recovery of free phase oil	Yes ☐	No ☐	
Booming	Yes ☐	No ☐	
Wild life rehabilitation	Yes ☐	No ☐	
Dispersant application	Yes ☐	No ☐	
Section 7 - Oil Spill Model Request			
Spill Modeling?	Trajectory	Surface 2D ☐	Sub-surface 3D ☐ Not at this time ☒

Additional information (please use start date and time)

At about 1900 hours on September 21st, 2022 Oil Leak from 6 inch Oil Pipeline Owned and operated by Universal Energy Resources Limited (UERL) was reported by a third party Community Personnel. UERL engaged the Community Pipeline Surveillance Contractor to Secure the Location.

Section 8- Equipment

On Site

Equipment in the Process of being mobilized.

REPORTING OFFICER:

Ojubayo Salau

DESIGNATION:

HSE Manager

SIGNATURE:

f. Syjis

DATE:

22-09-2022

*RBA Report must be submitted within 24 Hours of the Spill Incidence.