

INCIDENT NUMBER: 1358322



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

☒ Oil Pollution

☒ Fire/Explosion

☒ Drilling Mud/Chemical Pollution

☒ Others (Specify)

3. Incident Details.

i. Date of Incident:

09/08/2023

ii. Date first reported:

09/08/2023

iii. Date of first investigation:

09/08/2023

iv. Date of follow-up investigation:

v. Time investigation started:

12:05 HRS

vi. Estimated quantity spilled:

4 BBLs

4. Site Details

i. Site/Location:

36" RUMUEKPE - NKPOKU TNP RUMUEKPE COMMUNITY, ENOHUA LGA, R/S

ii. Position of Spill/Leak:

N 4.973, E 6.712 26

iii. Spill area

☒ Land

☒ Swamp

☒ Freshwater

☒ Mangrove

☒ Coastline

☒ Near shore

☒ Offshore

☒ Others (Specify)

iv. Structural Controls in Place

☒ Boom

☒ Trenches

☒ Bund Wall

☒ Sorbents

☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock

☒ 10 O'Clock

☒ 2 O'Clock

☒ 3 O'Clock

☒ 4 O'Clock

☒ 5 O'Clock

☒ 6 O'Clock

ii. Type of Oil Contaminant

☒ Crude Oil

☒ Condensate

☒ Chemicals

☒ Refined Products

☒ Others (Specify)

iii. Facility

☒ Pipeline

☒ Flow Line

☒ Wellhead

☒ Manifold

☒ Flow Station

☒ Rig

☒ Storage Tank

☒ Compressor Plant

☒ Others (Specify)

iv. Cause of Spill

☒ Corrosion

☒ Equipment Failure

☒ Third Party Interference

☒ Accident

☒ Operational Error

☒ Others (Specify)

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks

☒ Drilled Holes

☒ Blasting

☒ Theft

☒ Acid

☒ Others (Specify)

2" Nipple installed illegally at 10 O'Clock position on a station of the 36" pipeline by unknown persons.

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
- ☒ Fish Pond
- ☒ Vegetation
- ☒ Fishing Net
- ☒ Surface water
- ☒ Venerable Objects
- ☒ Others (Specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation
- ☒ Oil stained fishing nets
- ☒ Dead floating fishes
- ☒ Dead floating crabs
- ☒ Withering of vegetation
- ☒ Others (Specify) N/A

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
- ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. RUMHEKPE

(b) Land (Indicate area in m²)

i. 0.063Ha (30m²)

- ii. _____
- iii. _____
- iv. _____

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation

SPDC should carry out repair and clean-up the affected area immediately and also improve on its facility surveillance

12. Time Investigation ended 14:45 HRS.