



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		08172073919	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		016 / 2023	
Section 2 - Location			
State / LGA		Utue field OML 67 - /	
Coordinates of spill		EASTINGS 4Deg 11Min/46Secs N NORTHINGS 8Deg 13Min/60Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		10/7/2023 Time: 15:30 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Unknown: FSV Mediator 4 reported sheen around Utue KA/KB. Operations personnel visited Utue KA/KB and confirmed source of sheen was unknown.	
Status of spill		☐ Contained ☐ Not Contained ☒ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Location was visited and inspected, source of sheen not from Utue KA/KB.	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Sulphur Content		

	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat
☐ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release			
		Per Hour		☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00860bbl of unknown material based on sheen appearance			
	Coverage				
	Direction of travel				

Section 5 - Weather

METEOROLOGICAL DATA

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	North East	
Initial Wind Speed	2knots	
Air Temperature (C or OF)	30°C	
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	

Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐ No ☒
Recovery of free phase oil	Yes ☐ No ☒
Booming	Yes ☐ No ☒
Wild life rehabilitation	Yes ☐ No ☒
Dispersant application	Yes ☐ No ☒

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark Fraser
DESIGNATION: General Manager, Joint Venture Operations

DS
IE

DocuSigned by:
Mark W. Fraser
E80C423DA74246A...

SIGNATURE:

October 8, 2023

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*