



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization	Mandatory Information Required
Company Name	Mobil Producing Nigeria - MPN
Reporting Officer	Mark Fraser
Designation	General Manager, Joint Venture Operations
Phone Number	+2348172068193
Email Address	mark.w.fraser@exxonmobil.com
Incident Number	022 / 2023
Section 2 - Location	
State / LGA	Shoreline East of QIT – Ibeno LGA
Coordinates of spill	• Itio Eseh (N04°32'31.2", E008°12'59.2") • Ineh Atian (N04°32'21.7", E008°13'54.9") • Ineh Akpautong (N 04° 32' 12.3", E008° 14' 57.2") and • Itak Ibang (N 04° 32' 13.1", E 008° 17' 13.8")
	☐ Inland ☐ River ☐ Mangrove ☒ Shoreline ☐ Port ☐ Harbour ☐ Offshore ☐ Subsea ☐ Swamp Area ☐ Others
Depth of Water (if applicable)	
Section 3 – Spill Details	
Date and Time of spill	12/11/2023 Time: 12:30 hours local time
Source of spill – Facility	TRANSPORTATION FACILITIES – Not Applicable ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) – Not Applicable ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS – Not Applicable ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES – Not Applicable ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....
Cause of spill	Unknown: At about 12:30pm on December 11, 2023, during routine shoreline surveillance, personnel observed intermittent oiling along the beachfront at Itio Eseh (N04°32'31.2", E008°12'59.2") and Ineh Atian (N04°32'21.7", E008°13'54.9") communities, about 25km and 27km, respectively, East of QIT. Surveillance on December 12, 2023, showed oiling at two more communities - Ineh Akpautong (N 04° 32' 12.3", E008° 14' 57.2") and Itak Ibang (N 04° 32' 13.1", E 008° 17' 13.8"), about 29km and 33km, respectively, East of QIT. Overall, intermittent oiling was observed within an 8km distance between 25km & 33km East of QIT.

		Checks confirmed this oiling was not sourced from any MPN location. Source of oiling is unknown.			
Status of spill		☐ Contained ☐ Not Contained ☒ Unknown			
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify)... Reported observations to regulatory agencies Continued monitoring			
Product Data			☐ Persistent		☐ Non Persistent
	Product Name/Type				
	SG/API Gravity				
	Pour Point				
	Wax Content				
	Asphaltene				
	Sulphur Content				
	Viscosity				
Oil	Slick Locations(s)				
observation	Slick Dimension(s)				
	Orientation of slick(s)				
	Distribution of oil				
	Obvious odour				
Oil descriptions	Tarballs (tb)				
	Convergence line (co)				
	No structure (ns)				
	Windrows (wr)				
	Streamers (st)				
	Patches (pa)				
Oil color and appearance	Silver/grey				
	Rainbow				
	Metallic				
	Transitional				
	Dark				
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☒ On site ☒ Others: Vehicle			
Section 4 – Approximate Duration					
Release Rate	Instantaneous Release		Continuous Release		
			Per Hour		☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	Undetermined volume of oily material			
	Coverage				
	Direction of travel				
Section 5 - Weather					
METEOROLOGICAL DATA				NIMET weather forecast	
Wind Direction (wind direction given from)		North East			
Initial Wind Speed		1 knots			
Air Temperature (C or OF)		27°C			
Visibility Estimate		☒ Good ☐ Fair ☐ Poor			

Additional information (please use start date and time)

Section 8— Equipment	
On Site	