



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		001 / 2024	
Section 2 - Location			
State / LGA		Usari PP OML 67 - / Akwa Ibom State	
Coordinates of spill		EASTINGS 4Deg 13Min/51Secs N NORTHINGS 7Deg 46Min/54Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		1/14/2024 Time: 15:30 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others....	
Cause of spill		Equipment Failure: A sheen measuring 5m x 2500m was observed by personnel on Usari quarters around Usari B. Surfer 1942 was dispatched with O&M personnel to confirm, investigate, and mitigate the leak. Upon arrival at Usari B, the team observed bubbles from underwater vent stack line. The platform was shut-in and secured and the leaks stopped. MV Johanna II was dispatched to conduct mechanical agitation.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Mechanical agitation conducted.	
Product Data	☐ Persistent		☐ Non-Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		

	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release		
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.08569 bbl of crude oil based on sheen appearance		
	Coverage	About 2500m X 5m of 10% light brown and 90% silvery sheen on sea water		
	Direction of travel	Southwest		

Section 5 - Weather

METEOROLOGICAL DATA		NIMET weather forecast
Wind Direction (wind direction given from)	South west	
Initial Wind Speed	9.66knots	
Air Temperature (C or OF)	28.3°C	
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA		
Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (0C or 0F)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☒	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐

