



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		0817 207 3919	
Email Address		Mark.w.fraser@exxonmobil.com	
Incident Number		003/2024	
Section 2 - Location			
State / LGA		Yoho YPOML 104	
Coordinates of spill		4. 9' N 7. 29.45' E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		1/28/2024 Time: 06:56 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☒ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Unknown: Unknown: At about 0656hrs, hydrocarbon leak was sighted from Yoho YB wellhead platform with contact to the environment. Cause of leak yet to be determined - Assessment ongoing	
Status of spill		☐ Contained ☐ Not Contained ☒ Unknown.	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify)... Mechanical Agitation applied to disperse sheen. Field operator and Supervisor carried out leak assessment from the deck of Surfer 2604 FSV deployed for monitoring.	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type	NA	NA
	SG/API Gravity	NA	NA
	Pour Point	NA	NA
	Wax Content	NA	NA

	Asphaltene	NA	NA
	Sulphur Content	NA	NA
	Viscosity	NA	NA
Oil	Slick Locations(s)	NA	NA

observation	Slick Dimension(s)	NA	NA
	Orientation of slick(s)	NA	NA
	Distribution of oil	NA	NA
	Obvious odour	NA	NA
Oil descriptions	Tarballs (tb)	NA	NA
	Convergence line (co)	NA	NA
	No structure (ns)	NA	NA
	Windrows (wr)	NA	NA
	Streamers (st)	NA	NA
	Patches (pa)	NA	NA
Oil color and appearance	Silver/grey	NA	NA
	Rainbow	NA	NA
	Metallic	NA	NA
	Transitional	NA	NA
	Dark	NA	NA
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☒ Boat ☒ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release			
	NA	Per Hour	NA	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	Volume TBD			
	Coverage	TBD			
	Direction of travel	Current direction - SW			

Section 5 - Weather

METEOROLOGICAL DATA

Wind Direction (wind direction given from)	Southwest	NIMET weather forecast
Initial Wind Speed		
Air Temperature (C or OF)		
Visibility Estimate	☐ Good ☐ Fair ☒ Poor	

OCEANOGRAPHIC DATA


Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	NA Yes ☐ No ☐
Recovery of free phase oil	NA Yes ☐ No ☐
Booming	NA Yes ☐ No ☐
Wild life rehabilitation	NA Yes ☐ No ☐
Dispersant application	NA Yes ☐ No ☐

Section 6 – Pre-Entry Activities

Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---


Additional information (please use start date and time)	
DocuSigned by:  477C9840C4964BC... January 29, 2024	

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark Fraser.

DESIGNATION: General Manager Joint Venture Operations

SIGNATURE:

DocuSigned by:

E8DC423DA7A26A

.....

DATE: January 29, 2024

*RBA Report must be submitted within 24 Hours of the Spill Incidence.