



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Esso Exploration and Production Nigeria Limited -EENL	
Reporting Officer		Kyle Howlett	
Designation		General Manager Deepwater Operations (Acting)	
Phone Number		08172068400	
Email Address		kyle.a.howlett@exxonmobil.com	
Incident Number		004/2024	
Section 2 - Location			
State / LGA		Erha FPSO OML 133 - /	
Coordinates of spill		EASTINGS 5Deg 31Min/4Secs N NORTHINGS 4Deg 30Min/5Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		4/4/2024 Time: 16:30 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulklane ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☒ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Other: Oil sheen observed around disposal caisson at FPSO Port side during dewatering of Off spec tank 4C. Dewatering was immediately suspended and sheen stopped	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others: Dewatering was immediately suspended and sheen dissipated by ocean waves.	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
Sulphur Content			

Oil color and appearance	Silver/grey		25% of sheen		
	Rainbow		5% of sheen		
	Barely Discernible colours		15% of sheen		
	Clear water		55% of sheen		
	Dark				
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☒ On site ☐ Others.....			
Section 4 – Approximate Duration					
Release Rate	Instantaneous Release		Continuous Release		
		Per Hour		☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00092 of crude oil based on sheen appearance BARRELS			
	Coverage				
	Direction of travel				
Section 5 - Weather					
METEOROLOGICAL DATA					NIMET weather forecast
Wind Direction (wind direction given from)		South East			
Initial Wind Speed		4.2 Knots			
Air Temperature (C or OF)		27 DEG Celcius			
Visibility Estimate		☒ Good ☐ Fair ☐ Poor			
OCEANOGRAPHIC DATA					
Water Current Speed		0.2			
Tide Phase: Flood		High ☐ Ebb ☐			
Water Temperature (OC or OF)					
High Tide Time					
Source					
Section 6 – Pre-Entry Activities					
Mechanical cleaning		Yes ☐	No ☐		
Recovery of free phase oil		Yes ☐	No ☐		
Booming		Yes ☐	No ☐		
Wild life rehabilitation		Yes ☐	No ☐		
Dispersant application		Yes ☐	No ☐		
Section 6 – Pre-Entry Activities					
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐		

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

DocuSigned by:

Iniolong Udofe

312A1DA1D3A54AA...

April 5, 2024

REPORTING OFFICER: Kyle Howlett

DESIGNATION: General Manager Deepwater Operations (Acting)

DocuSigned by:

Kyle Howlett

26D2B18530184AE...

SIGNATURE:

April 5, 2024

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*