



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark W. Fraser	
Designation		General Manager Joint Venture Operations	
Phone Number		0817 207 3917	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		007 / 2024	
Section 2 - Location			
State / LGA		Akwa Ibom / Ibeno	
Coordinates of spill		EASTINGS 4Deg 8Min/9Secs N NORTHINGS 7Deg 58Min/4Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		4/8/2024 Time: 07:35 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☒ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☒ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Corrosion: At about 7:35 am of 8th April 2024, Operations technician on duty rounds noticed oil and gas mixture leaking from a 2" line on QA test separator. The test separator was isolated & depressurized since there was no flowing wells on QA. The leak has stopped.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others: Equipment was Isolated and depressurized ☒ Others (specify)..... [Precautionary Measures]	
Product Data	☐ Persistent		☐ Non-Persistent
	Product Name/Type	NA	NA
	SG/API Gravity		NA
	Pour Point	NA	NA

	Wax Content	NA	NA
	Asphaltene	NA	NA
	Sulphur Content	NA	NA
	Viscosity	NA	NA
Oil	Slick Locations(s)	NA	NA

observation	Slick Dimension(s)	NA	NA
	Orientation of slick(s)	NA	NA
	Distribution of oil	NA	NA
	Obvious odour	NA	NA
Oil descriptions	Tarballs (tb)	NA	NA
	Convergence line (co)	NA	NA
	No structure (ns)	NA	NA
	Windrows (wr)	NA	NA
	Streamers (st)	NA	NA
	Patches (pa)	NA	NA
Oil color and appearance	Silver/grey	NA	NA
	Rainbow	NA	NA
	Metallic	NA	NA
	Transitional	NA	NA
	Dark	NA	NA

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat
☒ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release		
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00162 bbls of crude oil based on sheen appearance		
	Coverage	About 80m X 30m of 1% light brown, 7% silvery sheen and 95% Clear Sea water		
	Direction of travel			

Section 5 - Weather

METEOROLOGICAL DATA

Wind Direction (wind direction given from)	Southeast
Initial Wind Speed	4 Knots
Air Temperature (C or OF)	25 DEG Celsius
Visibility Estimate	☒ Good ☐ Fair ☐ Poor

Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)	22 DEG Celsius	
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐ No ☐
Recovery of free phase oil	Yes ☐ No ☐
Booming	Yes ☐ No ☐


Wildlife rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☐	No ☒
Section 6 – Pre-Entry Activities		
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐ Not at this time ☐

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

DocuSigned by:  David McCord
REPORTING OFFICER: Mark W. Fraser
E08F5FB021DD4FA...

DESIGNATION: General Manager Joint Venture Operations

SIGNATURE:  **DATE:** April 8, 2024
150704B3DE2A47D.....

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*