



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization	Mandatory Information Required
Company Name	Mobil Producing Nigeria Unlimited (MPN)
Reporting Officer	Mark W. Fraser
Designation	General Manager Joint Venture Operations
Phone Number	0817 207 3917
Email Address	Mark.w.fraser@exxonmobil.com
Incident Number	010/2024
Section 2 - Location	
State / LGA	OML 67
Coordinates of spill	Lat.04*10.423'N Long.008*11.783'E
	☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others
Depth of Water (if applicable)	
Section 3 – Spill Details	
Date and Time of spill	5/21/2024 Time: 07:04 hours local time
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☒ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....
Cause of spill	Unknown (Mystery). Security patrol reported unknown burning barge around MPN Utue B wellhead. Barge surrounded by yet to be determined volume of sheen
Status of spill	☐ Contained ☐ Not Contained ☒ Unknown
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☐ Others (specify)...

		Deployed AHT Lamnalco Magpie and CSV Princess Johanna 2 for emergency intervention support. Fire extinguished. NIMASA contacted and awaiting further directive	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type	NA	NA
	SG/API Gravity	NA	NA
	Pour Point	NA	NA
	Wax Content	NA	NA
	Asphaltene	NA	NA
	Sulphur Content	NA	NA
	Viscosity	NA	NA
Oil	Slick Locations(s)	NA	NA

observation	Slick Dimension(s)	NA	NA	
	Orientation of slick(s)	NA	NA	
	Distribution of oil	NA	NA	
	Obvious odour	NA	NA	
Oil descriptions	Tarballs (tb)	NA	NA	
	Convergence line (co)	NA	NA	
	No structure (ns)	NA	NA	
	Windrows (wr)	NA	NA	
	Streamers (st)	NA	NA	
	Patches (pa)	NA	NA	
Oil color and appearance	Silver/grey	NA	NA	
	Rainbow	NA	NA	
	Metallic	NA	NA	
	Transitional	NA	NA	
	Dark	NA	NA	
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☒ Boat ☐ On site ☐ Others.....		
Section 4 – Approximate Duration				
Release Rate	Instantaneous Release		Continuous Release	
	NA		Per Hour	NA ☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	Yet to be determined		
	Coverage	Yet to be determined		
	Direction of travel	Current direction - SE		
Section 5 - Weather				
METEOROLOGICAL DATA				NIMET weather forecast
Wind Direction (wind direction given from)		SE from security boat		
Initial Wind Speed		0.3Knots		
Air Temperature (C or OF)		Unknown		
Visibility Estimate		☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA				
Water Current Speed				

Tide Phase: Flood	High ☐	Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning	NA Yes ☐	No ☐	
Recovery of free phase oil	NA Yes ☐	No ☐	
Booming	NA Yes ☐	No ☐	
Wild life rehabilitation	NA Yes ☐	No ☐	
Dispersant application	NA Yes ☐	No ☐	
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)	
DocuSigned by:  11919F9F802F434... May 22, 2024	

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark W. Fraser.

DESIGNATION: General Manager Joint Venture Operations

DocuSigned by:



SIGNATURE:E80C423DA74246A.....

May 22, 2024

DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*

