



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Esso Exploration and Production Nigeria Limited -EENL	
Reporting Officer		Kyle Howlett	
Designation		General Manager Deepwater Operations	
Phone Number		+2348172068400	
Email Address		Kyle.a.howlett@exxonmobil.com	
Incident Number		006/2024	
Section 2 - Location			
State / LGA		Erha FPSO OML 133 - /	
Coordinates of spill		EASTINGS 5Deg 21Min/4Secs N NORTHINGS 4Deg 20Min/5Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		6/3/2024 Time: 15:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☒ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Unknown: Oil sheen was observed around Erha overboard water disposal caisson.	
Status of spill		☐ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others: Implemented process isolations to stop the sheen Observed the sheen dissipated and the sea state cleared Investigation ongoing to determine the root cause and corrective actions	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		

observation	Slick Dimension(s)		
-------------	--------------------	--	--

	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☒ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.10063bbl of crude oil based on sheen appearance	
	Coverage		
	Direction of travel		
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)			
Initial Wind Speed		13Knots	
Air Temperature (C or OF)		33 DEG Celsius	
Visibility Estimate		☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood		High ☐ Ebb ☐	
Water Temperature (OC or OF)			
High Tide Time			
Source			
Section 6 – Pre-Entry Activities			
Mechanical cleaning		Yes ☐	No ☐
Recovery of free phase oil		Yes ☐	No ☐
Booming		Yes ☐	No ☐
Wild life rehabilitation		Yes ☐	No ☐
Dispersant application		Yes ☐	No ☐
Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)

Section 8– Equipment	
On Site	



REPORTING OFFICER: Kyle Howlett
DESIGNATION: General Manager, Deepwater Operations

DocuSigned by:
Kyle Howlett

SIGNATURE:26D2B18530184AE.....

June 4, 2024
DATE:

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*