



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization	Mandatory Information Required
Company Name	Mobil Producing Nigeria Unltd
Reporting Officer	Mark Fraser
Designation	General Manager, Joint Venture Operations
Phone Number	0916 863 2180
Email Address	mark.w.fraser@exxonmobil.com
Incident Number	029 / 2024
Section 2 - Location	
State / LGA	Akwa Ibom State / Around Ubit PP / OML 67 - Offshore
Coordinates of spill	EASTINGS 8Deg 10Min/43.980Secs NORTHINGS 4Deg 18Min/00.505Sec
	☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others
Depth of Water (if applicable)	
Section 3 – Spill Details	
Date and Time of spill	11/27/2024 Time: 11:05 hours local time
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....
Cause of spill	Unknown (Mystery): MPN personnel on routine surveillance reported oil sheen drifting in northwesterly direction around Unam A (Ubit field).
Status of spill	☐ Contained ☐ Not Contained ☐ Unknown
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Checks across MPN facilities in the JV field revealed all operations were normal and there was no leak. Mechanical agitation was carried out using support vessels.

Product Data	☐ Persistent		☐ Non Persistent	
	Product Name/Type			
	SG/API Gravity			
	Pour Point			
	Wax Content			
	Asphaltene			
	Sulphur Content			
	Viscosity			
Oil	Slick Locations(s)			
observation	Slick Dimension(s)			
	Orientation of slick(s)			
	Distribution of oil			
	Obvious odour			
Oil descriptions	Tarballs (tb)			
	Convergence line (co)			
	No structure (ns)			
	Windrows (wr)			
	Streamers (st)			
	Patches (pa)			
Oil color and appearance	Silver/grey			
	Rainbow			
	Metallic			
	Transitional			
	Dark			
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....		
Section 4 – Approximate Duration				
Release Rate	Instantaneous Release		Continuous Release	
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	To be determined (TBD).		
	Coverage	Intermittent patches of light brown and rainbow colors on the sea		
	Direction of travel	Northwest		
Section 5 - Weather				
METEOROLOGICAL DATA			NIMET weather forecast	
Wind Direction (wind direction given from)	Southwest			
Initial Wind Speed	14knots			
Air Temperature (C or OF)	29°C			
Visibility Estimate	☒ Good ☐ Fair ☐ Poor			
OCEANOGRAPHIC DATA				
Water Current Speed				
Tide Phase: Flood	High ☐	Ebb ☐		
Water Temperature (OC or OF)				
High Tide Time				
Source				
Section 6 – Pre-Entry Activities				
Mechanical cleaning	Yes ☐	No ☒		
Recovery of free phase oil	Yes ☐	No ☒		

Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☒
Dispersant application	Yes ☐	No ☒
Section 6 – Pre-Entry Activities		
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐ Not at this time ☐

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark Fraser
DESIGNATION: General Manager, Joint Venture Operations

DS
 1E

Signed by:
 Mark W. Fraser
 E80C423DA74246A.....

November 28, 2024
DATE:

SIGNATURE:

*RBA Report must be submitted within 24 Hours of the Spill Incidence.