



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: OMDO ENERGY RESOURCES NIGERIA LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
 ☒ Others (Specify) ILLEGAL CONNECTION

3. Incident Details

- i. Date of Incident: 2/1/2025
 ii. Date first reported: 2/1/2025
 iii. Date of first investigation: 2/1/2025
 iv. Date of follow-up investigation:
 v. Time investigation started: 11:46 HRS
 vi. Estimated quantity spilled:

4. Site Details

- i. Site/Location: 18" OBAMA-BRASS PIPELINE AT OMI-BUGO
 ii. Position of Spill/Leak: N 04° 27' 31.1" E 006° 15' 42.3"

iii. Spill area

- ☒ Land
 ☒ Swamp
 ☒ Freshwater
 ☒ Mangrove
 ☒ Coastline
☒ Near shore
 ☒ Offshore
 ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom
 ☒ Trenches
 ☒ Bund Wall
 ☒ Sorbents
 ☒ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
 ☒ 10 O'Clock
 ☒ 2 O'Clock
 ☒ 3 O'Clock
☒ 4 O'Clock
 ☒ 5 O'Clock
 ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil
 ☒ Condensate
 ☒ Chemicals
 ☒ Refined Products
☒ Others (Specify) N/A

iii. Facility

- ☒ Pipeline
 ☒ Flow Line
 ☒ Wellhead
 ☒ Manifold
 ☒ Flow Station
 ☒ Rig
☒ Storage Tank
 ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion
 ☒ Equipment Failure
 ☒ Third Party Interference
 ☒ Accident
☒ Operational Error
 ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
 ☒ Drilled Holes
 ☒ Blasting
 ☒ Theft
 ☒ Acid
☒ Others (Specify) ILLEGAL CONNECTION

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify) *N/A*

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify) *N/A*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW
 ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation... JUV WAS CONDUCTED AND CARRIED
OUT SUCCESSFULLY ON THE 2/1/2025. THE INCIDENT WAS
AS A RESULT OF THIRD PARTY INTERFERENCE.

12. Time Investigation ended.....