



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) CONDENSATE

3. Incident Details

- i. Date of Incident: 26/07/2024 ii. Date first reported: 26/07/2024
 iii. Date of first investigation: 26/07/2024
 iv. Date of follow-up investigation: N/A
 v. Time investigation started: 12:00 HRS
 vi. Estimated quantity spilled: 0.063 BBL (MOPPED UP)

4. Site Details

- i. Site/Location: 6" OSBOMBIRI/IFBIDABA PIPELINE AT OKPOTUARI
 ii. Position of Spill/Leak: N 04° 46' 00.4" E 005° 58' 44.2"

iii. Spill area

- ☒ Land
 ☒ Swamp
 ☒ Freshwater
 ☒ Mangrove
 ☒ Coastline
☒ Near shore
☐ Offshore
☒ Others (Specify).....

iv. Structural Controls in Place

- ☐ Boom
☐ Trenches
☐ Bund Wall
☐ Sorbents
☐ Others (Specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock
☐ 10 0'Clock
☐ 2 0'Clock
☐ 3 0'Clock
☐ 4 0'Clock
☐ 5 0'Clock
☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil
☒ Condensate
☒ Chemicals
☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline
☒ Flow Line
☒ Wellhead
☒ Manifold
☒ Flow Station
☒ Rig
☒ Storage Tank
☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion
☒ Equipment Failure
☒ Third Party Interference
☒ Accident
☒ Operational Error
☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
☒ Drilled Holes
☒ Blasting
☒ Theft
☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
 Dead floating crabs
 Withering of vegetation
 Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation..... JOINT INVESTIGATION TEAM RECOMMENDED
THAT NAOC SHOULD ADDRESS THE ROOT CAUSE OF
SABOTAGE CASES

12. Time Investigation ended..... 13:40 HRS