



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 11/08/2024 ii. Date first reported: 11/08/2024
 iii. Date of first investigation: 11/08/2024
 iv. Date of follow-up investigation: N/A
 v. Time investigation started: 14:25
 vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 6th OSBOMBIRI/TEBIDARA PIPELINE AT AZUZUAMA
 ii. Position of Spill/Leak: NO 4° 14' 06.9" E 005° 58' 28.1"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock 7 TO 11 O'CLOCK

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify) N/A

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify) *N/A*

iii. Delineation of Impacted area

- ☒
- Within Company's facility/ROW
- ☒
- Outside Company's facility/ROW

7. Extent of Impact

(a) Community (*Indicate name*)

- i. _____
 ii. _____
 iii. _____
 iv. _____

(b) Land (*Indicate area in m²*)

- i.
ii.
iii.
iv.

(c) Creek/Creek lets

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

- ☐
- Tidal
- ☐
- Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation. NADC SHOULD INTENSIFY ITS
SURVEILLANCE TO CURB SABOTAGE CASES

12. Time Investigation ended.....

14:30 HRS