



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Seplat Energy Producing Nigeria Unlimited	
Reporting Officer		John Itsueli	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		JItsueli@seplatenergy.com	
Incident Number		021 / 2025	
Section 2 - Location			
State / LGA		Ubit PP / OML 68 - 04° 15 56.267'N - 08° 10 24.425'E	
Coordinates of spill		EASTINGS 04Deg 15Min/56.267Secs N NORTHINGS 8Deg 10Min/24.425Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		11/12/2025 Time: 12:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Equipment failure - During the production restoration after the I-Function SD, crude oil was observed coming out through the breather valve of Sep-B outlet SDV bonnet to the sea. The valve is suspected communicating with the process through the packing gland.	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others: Gas was introduced to push out the oil from the SDV Bonnet and leak stopped. Sheen dispersed completely same day November 12, 2025.	
Product Data	☐ Persistent		☐ Non-Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		

	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
Oil color and appearance	Patches (pa)		
	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☐ On site ☐ Others.....	

Section 4 – Approximate Duration

Release Rate	Instantaneous Release		Continuous Release	
			Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.006289 bbls of Crude Oil based on sheen appearance		
	Coverage	About 100m x 1m of 100% light brown sheen on the sea		
	Direction of travel	Southwest		

Section 5 - Weather

Section 5 - Weather		NIMET weather forecast
METEOROLOGICAL DATA		
Wind Direction (wind direction given from)	Northwest	
Initial Wind Speed		
Air Temperature (C or OF)		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	
OCEANOGRAPHIC DATA		
Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐	No ☐
Recovery of free phase oil	Yes ☐	No ☐
Booming	Yes ☐	No ☐
Wild life rehabilitation	Yes ☐	No ☐
Dispersant application	Yes ☐	No ☐

Section 6 – Pre-Entry Activities


Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐
---------------------------	-------------------------------------	---	---

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: John Itsueli
DESIGNATION: General Manager, Joint Venture Operations

Initial


Signed by:


SIGNATURE:31AFB6B4837644A.....

DATE:13-Nov-25 | 14:43 WAT.....

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*